

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 3377 From entrance to location



Photo # 3378 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



**Photo # 3382 Rill erosion on spur road**



**Photo # 3383 Rill erosion on spur road**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Mar 27, 2023 at 12:04:57 PM



Mar 27, 2023 at 12:05:15 PM  
CO

**Photo # 3384 Road degradation/transport of sediment**

**Photo # 3385 Culvert needs maintenance/Insufficient run on BMP's/transport of sediment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



**Photo # 3386 Culvert needs maintenance/Insufficient run on BMP's**



**Photo # 3387 Culvert needs maintenance/Insufficient run on BMP's**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



**Photo # 3388 Gully/Rill erosion/Transport of sediment on spur road/road degradation**



**Photo # 3389 Gully/Rill erosion/Transport of sediment on spur road/road degradation**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 3390 Rill erosion & transport of sediment on spur road



Photo # 3391 Rill erosion & transport of sediment on spur road



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



**Photo # 3392 Rill erosion & transport of sediment on spur road**



**Photo # 3393 Rill erosion & transport of sediment on spur road**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



**Photo # 3394 Rill erosion & transport of sediment on spur road**