

Inspection Photos

API: 071-07085

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/27/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023

Inspection Photos



Photo 1. Facing south toward the access road stream crossing. There has been additional culverts installed and the embankment has been armored with rock rip/rap protection. Previous corrective action has been completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023

Inspection Photos



Photo 2. Facing south toward the access road stream crossing outlet side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023

Inspection Photos



Photo 3. Facing northwest toward the access road stream crossing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023

Inspection Photos



Photo 4. All disturbed areas along the road side have been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023

Inspection Photos



Photo 5. Facing southeast along the access road. The road side has been seeded and stabilized. The culverts are maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023

Inspection Photos



Photo 6. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07085 | Date: 3/27/2023