

Inspection Photos
Location Name: Firecracker
Spill ID: 481413



COGCC Inspection
40.06225, -104.94548, 5086.2ft, 276°
21/03/2023 12:43:12

Photo 1 – Excavation- note fencing blowing in background



COGCC Inspection
40.06226, -104.94549, 5081.5ft, 311°
21/03/2023 12:43:13

Photo 2 – Excavation- note silt fence failing in background

Inspection Photos
Location Name: Firecracker
Spill ID: 481413



Photo 3 – Excavation- note fencing blowing in background



Photo 4 – Clean soil stockpile- note fencing blowing in background

Inspection Photos
Location Name: Firecracker
Spill ID: 481413



Photo 5 – Contaminated soils stockpile



Photo 6 – Failed stormwater BMPs and trash

Inspection Photos
Location Name: Firecracker
Spill ID: 481413



Photo 7 – South Excavation Failed stormwater BMPs and contaminated soils overtopping berm.



Photo 8 – Fencing has degraded and become windblown trash in neighboring fields.