

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3420 From entrance to location



Photo # 3421 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3422 Location



Photo # 3423 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3424 Location



Photo # 3429 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3430 Meter calibration info not conspicuously posted



Photo # 3432 Rill erosion

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



**Photo # 3433 Lack of stabilization & erosion of cut slope/
insufficient BMP's**



**Photo # 3434 Lack of stabilization & erosion of cut slope/
insufficient BMP's**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3435 Lack of stabilization & erosion of cut slope /insufficient BMP's & insufficient run on controls/BMP's



Photo # 3436 Lack of stabilization & erosion of cut slope/ insufficient BMP's & insufficient run on controls/BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3439 Rill erosion/transport of sediment off location

Photo # 3440 Rill erosion/transport of sediment off location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3442 Rip Rap needs maintenance (NW area of location across from wellheads)



Photo # 3445 Rill erosion

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3446 Insufficient run on controls/BMP's