

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2023

Submitted Date:

03/22/2023

Document Number:

696204772

## FIELD INSPECTION FORM

 Loc ID 335795 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202
**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerus oilandgas.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275459	WELL	PR	03/01/2019	GW	045-13546	CHEVRON 42A-8D	RI
275466	WELL	PR	01/01/2023	GW	045-13547	CHEVRON 41D-8D	RI
335795	LOCATION	AC			-	CHEVRON-66S96W 8NENE	RI

**General Comment:**

On 3/21/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's CHEVRON-66S96W/8NENE Location in Garfield County, Colorado.

Location within a CPW High Priority Habitat area.

This inspection is a follow-up to #696204598 and #696204740 to document compliance with the following corrective actions:

- Inadequate Secondary Containment
- Stormwater: Location/access road lacks stabilization

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective actions

Refer to the "Location", "Reclamation" and "stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type			
comment:	See "Stormwater"		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	1-866-580-9382/911		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Paneling/Barbed wire combination		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal Pipe		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:	<input style="width: 900px;" type="text"/>					

Corrective Action:	Date:			
<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<p>Inspection #696204598 and #696204740 observed that secondary containment is not sufficiently impervious to contain spilled or released materials; various holes/tears observed throughout liner. Inspection required Operator to maintain BMP to ensure containment is sufficiently impervious to contain spill or release.</p> <p>It was observed in this inspection that operator appears to have patched the liner. This corrective action appears to have been addressed. Continue to monitor and maintain BMPs, so that containment remains sufficiently impervious.</p>			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 275459 Type: WELL API Number: 045-13546 Status: PR Insp. Status: RI

Facility ID: 275466 Type: WELL API Number: 045-13547 Status: PR Insp. Status: RI

Facility ID: 335795 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696204740 observed that BMPs to stabilize, as well as to minimize erosion, degradation, tracking and sediment transport are missing or insufficient at the North/South access road Leading to the Location; tracking/rutting apparent; BMPs to manage stormwater runoff missing or insufficient; sediment transport observed.

It was observed in this inspection that BMPs remain missing or insufficient along the access road. It was also observed that the Location now also lacks stabilization; BMPs to stabilize, as well as to minimize erosion, degradation and sediment transport during wet conditions remain missing or insufficient; tracking and degradation observed.

CA has not been addressed and remains applicable.

Corrective Action: **Comply with Rule 1002.f.(2): Install or repair required BMPs on the Location and access road.**

Date: 03/11/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403353324	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058914">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058914</a>
696204775	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058905">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6058905</a>