

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2023

Submitted Date:

03/29/2023

Document Number:

707900926

FIELD INSPECTION FORMLoc ID 336221 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240309	WELL	PR	01/01/2023	OW	123-08097	COSSLETT 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is faded and may need to be repaired in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Snow fence around open holes next to well head.		
Corrective Action:	(Fence) Secure access to excavation in compliance with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v	Date:	04/05/2023

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240309 Type: WELL API Number: 123-08097 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: This well is shut in and has been shut in due to line repairs. Operator is showing gas production 2 times in the last year submit proper reports and up date status. Flow lines are in the closed position at time of inspection.

Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday March 29, 2023 at approximately 9:45AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Cosslett #1</p> <p>Operator: KP Kauffman</p> <p>API#: 123-08097</p> <p>County: Weld</p> <p>While there, I observed a Shut in well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Fence: Rule Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v Corrective action 4-5-23 date of see Photos</p> <p>Weather conditions: Clear</p> <p>Just to the east of the well head there is open pot holes showing flow lines. Snow fence is in disrepair.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverrr	03/29/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900927	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6065517