

Final Reclamation and Stormwater Inspection

Date: 03/23/2023

Operator: P O & G OPERATING LLC - 10634

Location ID: 324938 & 463250

Inspection Document #: 708200072

Kit Carson County, CO

NWNE Section 14 T11S R46W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 1. Facing southwest at location entrance. Photo provides an overview of the location in its present state, at the time of inspection. It does not appear any reclamation work has been attempted since the last inspection on 08/28/2019 (Doc #696200704). Culvert and access road remain, highlighted in red.

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photos 2 & 3. Facing east from the eastern portion of the location. Photo illustrates that equipment remains on location and has not been removed as part of the reclamation process, as mentioned in previous inspections. The equipment needs to be removed regardless of ownership.

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 4. Facing northeast from the southwestern portion of the location. Photo illustrates subsidence (red) and presence of undesirable vegetation (e.g. kochia) observed near the former tank location.

Inspection Photos

Location Name: Lowe-611S64W

Location ID: 324938 & 463250



Photo 5. Facing northeast from the center/western portion of the location. Overview of location with presence of undesirable vegetation and bare areas where road base/gravel remains.

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 6. See comments in Photo 5.

Inspection Photos

Location Name: Lowe-611S64W

Location ID: 324938 & 463250



Photo 7. Facing south from approximate center of location. Location is predominantly undesirable vegetation (e.g. kochia).

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 8. Facing south near PA well API 063-06192. Photo illustrates that the access road to the well has not been reclaimed with the presence of road base and gravel throughout.

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250




Photo 9. Facing southwest near the PA well. Subsidence (red) was observed in addition to undesirable vegetation, debris, road base/gravel, and equipment. It does not appear any additional reclamation work has been performed since the last inspection on 08/28/2019 (Doc #696200704).

Inspection Photos

Location Name: Lowe-611S64W

Location ID: 324938 & 463250



Photos 10 & 11. Equipment and debris observed on location that will need to be removed in addition to final reclamation activities.

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 12. Facing northeast from the PA well. Photo illustrates that road base/gravel remain on location and presence of undesirable vegetation (e.g. kochia).

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 13. Close up photo of Photo 12.

Inspection Photos
Location Name: Lowe-611S64W
Location ID: 324938 & 463250



Photo 14. Facing north from PA well; access road has not been reclaimed.



Photo 15. Google Earth aerial imagery illustrating the access roads (red) that remain and will need to be reclaimed per Rule 1004. Previous inspection (Doc #696200704) provided photos showing that the lease/access road did not exist pre-oil and gas development.