


# Storm Water Management and Erosion control

**Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW**

**Location #: 334772**



**Location Overview: Location is located in a 411 a. internal buffer zone.**  
**Additionally approximately 30 yards from the Colorado River.**  
**Section/Township/Range: 35 6S95W**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW**  
**Location #: 334772**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW**  
**Location #: 334772**



**Photo #9415 Location lacks stabilization.**



**Photo #9416 Location lacks stabilization.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW**  
**Location #: 334772**



**Photo #9417 Location lacks stabilization.**



**Photo #9418 location lacks stabilization.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW**  
**Location #: 334772**



**Photo #9419 Location lacks stabilization.**



**Photo #9425 Insufficient tracking BMP at entrance to location.**

**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC DERE-66S95W /35SWSW**  
**Location #: 334772**

Network: Mar 30, 2023 at 11:41:20 AM M



**Photo #9426 Insufficient tracking BMP at entrance to location.**