

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Mar 31, 2023 at 10:41:21 AM
CO



Mar 31, 2023 at 10:42:16 AM
CO

Photo # 3957 From entrance to location

Photo # 3958 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Photo # 3965 Lack of stabilization/compaction/insufficient tracking BMP's



Photo from Inspection 700703983 conducted on 03/17/2022

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Photo # 3970 Lack of stabilization/compaction/insufficient tracking BMP's



Photo from Inspection 700703983 conducted on 03/17/2022

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Photo # 3964 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3969 Lack of stabilization/compaction/insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Photo # 3971 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 3959 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Photo # 3960 Failure to minimize surface disturbance



Photo # 3977 Failure to minimize surface disturbance



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-20 pad

Location ID: 335342



Photo # 3978 Failure to minimize surface disturbance