

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2023

Submitted Date:

03/24/2023

Document Number:

695107793

FIELD INSPECTION FORMLoc ID 307828 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257531	WELL	PR	09/01/2017	CBM	071-07017	STATE OF COLORADO AT 12-16 TR	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 5: WEEDS AROUND WELLHEAD AND EQUIPMENT.		
Corrective Action:	REMOVE ALL WEEDS AROUND ALL EQUIPMENT PER RULE606.		Date: 04/08/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	BOTH ARE PLUMBED TO SURFACE		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	257531	Type:	WELL	API Number:	071-07017	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	10/18/2011	Annual Brhd Completed?							
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: PHOTO 6: OILY WASTE IN TR WELL ENGINE SKID.
PHOTO 7: OILY WASTE IN ORIGINAL WELL ENGINE SKID.

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 03/28/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403356470	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062933
695107822	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062918