

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2023

Submitted Date:

03/24/2023

Document Number:

695107801

**FIELD INSPECTION FORM**Loc ID 334141 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273262	WELL	PR	02/01/2013	GW	071-08152	SKIP 23-10	PR
286161	WELL	PR	02/05/2007	CBM	071-08920	SKIP 23-10 TR	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL NEAR TR WELLHEAD. PHOTO 6: AREA OF IMPACTED SOIL NEAR TR WELL PRIME MOVER SKID. PHOTO 7: AREA OF IMPACTED SOIL NEAR ORIGINAL WELL PRIME MOVER SKID. PHOTO 8: AREA OF IMPACTED SOIL NEAR TR WELL COMPRESSOR SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D.		Date: 04/08/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 2		corrective date
Comment:	BOTH ARE ACCESSABLE		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 7		
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 273262 Type: WELL API Number: 071-08152 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/13/2011Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 286161 Type: WELL API Number: 071-08920 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/14/2011Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: PHOTO 9: OILY WASTE IN ORIGINAL WELL ENGINE SKID.  
 PHOTO 10: OILY WASTE IN TR WELL COMPRESSOR SKID.

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 03/28/2023

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 279852 Lat: 37.271021 Long: -104.769997

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403356475	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062939">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062939</a>
695107824	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062922</a>