

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE

Location ID: 334825



Photo #9432 From entrance to location.



Photo #9433 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE

Location ID: 334825



Photo #9435 Calibration cards not conspicuously posted



Photo #9444 Well W 15-5 wellhead leaking.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /5NWSE

Location ID: 334825



Photo #9445 Well W 15-5 wellhead leaking