

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



Photo # 3732 From entrance to location



Photo # 3733 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



Photo # 3734 Location



Photo # 3735 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



Photo # 3736 Location



Photo # 3737 Meter calibration info not conspicuously posted



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3738 Containment capacity inadequate**



**Photo # 3739 Rill erosion & transport of sediment (NW area of location near production tank containment)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3740 Rill erosion & transport of sediment (NW area of location near production tank & containment)**



**Photo # 3742 Rill erosion & transport of sediment (NW area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3745 Rill erosion & transport of sediment (NW area of location)**



**Photo # 3746 Rill erosion & transport of sediment (NW area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3748 Sediment Trap needs maintenance (NW area of location)**



**Photo # 3749 Check dam needs maintenance (NW area near sediment trap)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3750 Check dam needs maintenance (NW area near sediment trap)**



**Photo # 3753 Rill erosion & transport of sediment (SW area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3754 Check dam needs maintenance**



**Photo # 3758 Check dam needs maintenance (SW area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3760 Check dam needs maintenance (SW area of location)**



**Photo # 3763 Lack of stabilization/Rill & Gully erosion/transport of sediment onto location/insufficient run on controls/BMP's (East side of location on slope)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



Mar 30, 2023 at 12:14:06 PM  
CO

**Photo # 3764 Lack of stabilization/Rill & Gully erosion/transport of sediment onto location/insufficient run on controls/BMP's (East side of location on slope)**



Mar 30, 2023 at 12:14:16 PM  
CO

**Photo # 3765 Lack of stabilization/Rill & Gully erosion/transport of sediment onto location/insufficient run on controls/BMP's (East side of location on slope)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3766 Lack of stabilization/Rill & Gully erosion/transport of sediment onto location/insufficient run on controls/BMP's (East side of location on slope)**



**Photo # 3767 Rill erosion (NE area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3769 Check dam needs maintenance (NE area of location)**



**Photo # 3770 Check dam needs maintenance (NE area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



Photo # 3771 Rill erosion (SE area of location)



Photo # 3773 Check dam & ditch need maintenance (East side of location)



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3778 Rill erosion (NE area of location)**



**Photo # 3779 Ditch needs maintenance (NE area of location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



Photo # 3780 Rill erosion (NE area of location)



Photo # 3782 Check dam needs maintenance (NE area of location)



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3783 Rill erosion (NW area of location near entrance)**



**Photo # 3784 Rill erosion (NW area of location near entrance)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3785 Sediment trap needs maintenance (North side of spur road approximately 60 yards from location)**



**Photo # 3786 Sediment trap needs maintenance (North side of spur road approximately 60 yards from location)**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3787 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 3788 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3789 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 3790 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad

Location ID: 324122



**Photo # 3791 Sediment trap needs maintenance (North side of spur road approximately 150-200 yards from entrance to location)**



**Photo # 3792 Sediment trap needs maintenance (North side of spur road approximately 150-200 yards from entrance to location)**