

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2023

Submitted Date:

04/03/2023

Document Number:

708900206

FIELD INSPECTION FORM

Loc ID: 324122 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 18 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257824	WELL	PR	06/30/2000	GW	045-07600	CLOUGH RMV 137-27	PR

General Comment:

COGCC Inspection Report Summary
On 03/30/2023 at approximately 11:51 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad. Location # 324122 in Garfield County Colorado. Location is within High Priority Habitat area & Bald Eagle Nest & Roost sites as well as within close proximity to NSO/Density Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Meter calibration info not conspicuously posted with a CA date of 04/13/2023
2. Stormwater - Sediment traps, Ditches & Check dams need maintenance, Rill & Gulley erosion/transport of sediment, Insufficient run on & run off controls/BMP's with a CA date of 04/18/2023
3. Tanks & Berms - Containment capacity inadequate - containment contains a large amount of stormwater with a CA date of 05/03/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:

Equipment:		corrective date
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible	
Corrective Action:		Date:
Type: Deadman # & Marked	# 3	
Comment:	Marked	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Meter calibration info not conspicuously posted	
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date: 04/13/2023
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:	Well on plunger lift	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Containment capacity inadequate - containment contains a large amount of stormwater.			
Corrective Action:	Properly maintain tank containment			Date: 05/03/2023

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 257824 Type: WELL API Number: 045-07600 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
		Sediment Traps	Fail			
Ditches	Fail					
Gravel						
		Rip Rap				
Compaction						Light
Rip Rap						
Other	Fail					Rill/Gully erosion/insufficient run on controls/BMP
		Gravel				Sparse
		Ditches	Fail			
Check Dams	Fail					
		Compaction				Light
Sediment Traps	Fail					

- Comment:
1. Rill/Gully erosion/transport of sediment/insufficient run on & run off controls/BMP's
 2. Sediment traps on location & spur road need maintenance
 3. Ditches on location maintenance
 4. Ditch coming out of sediment trap on spur road needs maintenance/gully erosion & transport of sediment/insufficient run off controls/BMP's
 5. Check dams need maintenance

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Date: 04/18/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment, Tanks & Berms & Stormwater for observed compliance issues.	smelserw	04/01/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900207	Inspection 708900206 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070582