

Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323973

Location Name: SAVAGE-66S94W/28SESW

Inspection Document #: 702801410

Garfield County, CO

SESW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-66S94W/28SESW
Location ID: 323973



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: SAVAGE-66S94W/28SESW
Location ID: 323973



Photo 2. Photos show production areas. Note the sediment that has been transported from the southern interim area around the wellhead (right).

Inspection Photos

Location Name: SAVAGE-66S94W/28SESW

Location ID: 323973



Photo 3. Photos show lack of stabilization of the western interim area resulting in sheet erosion and sediment transport (left) and offsite degradation (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801410

Inspection Photos
Location Name: SAVAGE-66S94W/28SESW
Location ID: 323973



Photo 4. Photos show soils in the southern interim area are bare and unstabilized (left) resulting in rill erosion (right).



Inspection Photos
Location Name: SAVAGE-66S94W/28SESW
Location ID: 323973



Photo 5. Photo shows the stormwater ditch at the south of the location is full of sediment lost from the southern interim area. Note rills in interim area and degradation to the stormwater ditch and rock check dam.



Photo 6. Photo shows sheet and rill erosion and sediment transport from the unstabilized southern interim area.

Inspection Photos
Location Name: SAVAGE-66S94W/28SESW
Location ID: 323973



Photo 7. Photo shows the transition between stabilized, vegetated areas to the south of the location and unstabilized, bare areas in the southern interim area.

Inspection Photos

Location Name: SAVAGE-66S94W/28SESW

Location ID: 323973



Photo 8. Photo shows an overview of the northern interim area including a stormwater ditch/slope drain. Northern interim areas are partially vegetated, however, erosion degradation is present.



Photo 9. Photo shows degradation in the stormwater ditch/slope drain at the north of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801410

Inspection Photos
Location Name: SAVAGE-66S94W/28SESW
Location ID: 323973



Photo 10. Photo shows pedestaling around vegetation in the northern interim area indicating erosion.



Photo 11. Photo shows pedestaling and a rill in the northern interim area indicating erosion.