

Inspection Photos

March 29, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324048

Location Name: FORCE-66S94W/33NWSE

Inspection Document #: 702801416

Garfield County, CO

NWSE Section 33 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 1. Photo taken from the west shows an overview of the location.

Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 2. Photos show production areas. Note stained gravel at the wellhead (left).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801416

Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 3. Photos show bull thistle (List B Noxious) in the southern interim area.



Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 4. Photo shows the eroding cut to the east and sediment laden stormwater flowing at the base of the cut.




Photo 5. Photo shows rill erosion on the eastern cut slope.



Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 6. Photos show sediment accumulating at the base of the eastern cut slope. Erosion is resulting in degradation to the slope, smothering vegetation below and contributing sediment loads to stormwater.



Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 7. Photo shows sloughed soil accumulating at the base of the southeastern cut slope and covering vegetation. Note also exposed roots at the top of the cut also indicating soil loss.



Inspection Photos
Location Name: FORCE-66S94W/33NWSE
Location ID: 324048



Photo 8. Photos show southern (left) and western (right) interim areas.