

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2023

Submitted Date:

04/04/2023

Document Number:

690204055

**FIELD INSPECTION FORM**

Loc ID: 422357 Inspector Name: COSTA, RYAN On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 44390  
Name of Operator: JAVERNICK OIL  
Address: 3040 E MAIN  
City: CANON CITY State: CO Zip: 81212

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James		javernick1@gmail.com	
Javernick, Salene		salenej@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422358	WELL	SI	11/01/2022	OW	043-06204	CHANDLER CREEK 22-32	RI

**General Comment:**

On 3/20/2023, Ryan Costa conducted a location inspection.  
See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	new cattleguard was installed.	
Corrective Action			Date:

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment: <input style="width: 80%;" type="text"/>					
Corrective Action:					Date:

<b>Paint</b>	
Condition	<input style="width: 80%;" type="text"/>
Other (Content)	<input style="width: 80%;" type="text"/>
Other (Capacity)	<input style="width: 80%;" type="text"/>
Other (Type)	<input style="width: 80%;" type="text"/>

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Insufficient	Base Insufficient	
Comment: There was pro-panel installed around the tank but there is daylight at the base and the walls may not be sealed well enough for containment. For any significant modifications, secondary containment should have been installed per Rule 603.o.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 05/04/2023

<b>Venting:</b>			
Yes/No			
Comment:	<input style="width: 80%;" type="text"/>		
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:	<input style="width: 80%;" type="text"/>		

Corrective Action:		Date:	
--------------------	--	-------	--

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204056	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6071103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6071103</a>