

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4085 From entrance to location



Photo # 4088 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4086 Location



Photo # 4087 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046




Photo # 4089 Location



Photo # 4093 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4091 Rill erosion



Photo # 4096 Rill erosion & transport of sediment (near production unit)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4098 Rill erosion & transport of sediment off location (near production tank & containment)



Photo # 4099 Rill erosion & transport of sediment off location (near production tank & containment)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



**Photo # 3995 Transport of sediment/insufficient BMP's
(approximately 1.5 miles down lease road)**

**Photo # 3996 Transport of sediment/insufficient BMP's
(approximately 1.5 miles down lease road)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 3997 Rill erosion & transport of sediment off lease road (approximately 1.5 – 1.6 miles down lease road)



Photo # 3998 Rill erosion & transport of sediment off lease road (approximately 1.5 – 1.6 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4000 Transport of sediment/Insufficient run on controls /BMP's (approximately 1.5 – 1.6 miles down lease road)



Photo # 4001 Transport of sediment/Insufficient run on controls/ BMP's (approximately 1.5 – 1.6 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4003 Transport of sediment/Insufficient run on controls/BMP's (approximately 1.5 – 1.6 miles down lease road)



Photo # 4009 Transport of sediment off lease road & into vegetation (approximately 1.6 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4010 Sediment transport/insufficient BMP's (approximately 1.6 – 1.7 miles down lease road)



Photo # 4011 Photo # 4010 Sediment transport/insufficient BMP's (approximately 1.6 – 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4015 Sediment transported off lease road/insufficient BMP's (approximately 1.6 – 1.7 miles down lease road)



Photo # 4016 Sediment transported off lease road/insufficient BMP's (approximately 1.6 – 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4017 Sediment transported off lease road/insufficient BMP's (approximately 1.6 – 1.7 miles down lease road)



Photo # 4018 Sediment transported off lease road/insufficient BMP's (approximately 1.6 – 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4019 Lack of stabilization on slope/transport of sediment/insufficient BMP's (approximately 1.6- 1.7 miles down lease road)



Photo # 4020 Culvert & sediment trap need maintenance (approximately 1.6- 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



**Photo # 4021 Transport of sediment/insufficient BMP's
(approximately 1.7 miles down lease road)**



**Photo # 4022 Transport of sediment/insufficient BMP's
(approximately 1.7 miles down lease road)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4023 Sediment transported into vegetation



**Photo # 4024 Lack of stabilization/insufficient tracking
BMP's/insufficient run on controls/BMP's/transport of sediment
(approximately 1.7 miles down lease road)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4026 Insufficient BMP's/Sediment transported off lease road & into vegetation (approximately 1.6 – 1.7 miles down lease road)



Photo # 4027 Lack of stabilization/Insufficient tracking BMP's (approximately 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4028 Insufficient run on BMP's (approximately 1.6 – 1.7 miles down lease road)



Photo # 4029 Insufficient run on BMP's (approximately 1.6 – 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4030 Insufficient run on BMP's (approximately 1.6 – 1.7 miles down lease road)



Photo # 4031 Insufficient BMP's/Sediment transported off lease road & into vegetation near the Colorado River (approximately 1.7 – 1.8 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4032 Insufficient BMP's/Sediment transported off lease road & into vegetation near the Colorado River (approximately 1.7 – 1.8 miles down lease road)



Photo # 4033 Insufficient BMP's/Sediment transported off lease road & into vegetation (approximately 1.7 – 1.8 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4038 Lack of stabilization on slope/Insufficient run on controls/BMP's/transport of sediment (approximately 1.7 miles down lease road)



Photo # 4039 Lack of stabilization on slope/Insufficient run on controls/BMP's/transport of sediment (approximately 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4040 Lack of stabilization on slope/Insufficient run on controls/BMP's/transport of sediment (approximately 1.6 – 1.7 miles down lease road)

Photo # 4041 Lack of stabilization on slope/Insufficient run on controls/BMP's/transport of sediment (approximately 1.6 – 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4043 Lack of stabilization on slope/Insufficient run on controls/BMP's/transport of sediment (approximately 1.6 – 1.7 miles down lease road)



Photo # 4047 Lack of stabilization on slope/Insufficient run on controls/BMP's/transport of sediment (approximately 1.6 – 1.7 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



Photo # 4044 Culvert has insufficient BMP's, allows direct discharge into the Colorado River (approximately 1.8 – 1.9 miles down lease road)



Photo # 4045 Culvert has insufficient BMP's, allows direct discharge into the Colorado River (approximately 1.8 – 1.9 miles down lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



**Photo # 4080 Lack of stabilization/Insufficient tracking
BMP's (approximately 3.5 miles down lease road)**



**Photo # 4081 Lack of stabilization/Insufficient tracking
BMP's (approximately 3.5 miles down lease road)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEBSTER/HEATH RMV 236-28 pad

Location ID: 324046



**Photo # 4083 Lack of stabilization/Insufficient tracking
BMP's (approximately 3.8 miles down lease road)**

**Photo # 4084 Lack of stabilization/Insufficient tracking
BMP's (approximately 3.8 miles down lease road)**