

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2023

Submitted Date:

04/04/2023

Document Number:

693805471**FIELD INSPECTION FORM**Loc ID 312435 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 760 HORIZON DRIVE STE 400City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------|
| , " | 970-675-7928 | inspections@utahgascorp.com | All Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 221596 | WELL | TA | 01/01/2023 | OW | 077-08198 | GOVERNMENT 31-1 | SI |

General Comment:

COGCC staff performed a routine field inspection on 4/3/2023.

See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-675-4482

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Pipe fence | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Type: Horizontal Heated Separator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------------|---|-------|
| Type: Deadman # & Marked | # 4 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Flow Line | # 1 | |
| Comment: | 4" riser on SE corner of location property. | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | 39.312908,-108.921758 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 221596 | Type: | WELL | API Number: | 077-08198 | Status: | TA | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: Well shut in at time of inspection. | | | | | | | | | |
| Corrective Action: _____ Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 693805477 | Inspection photos 4/3/2023 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072012 |