

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7

Location #: 420224




Location Overview: Location is approximately 150 yards from the Colorado River.

Section/Township/Range: 7 7S95W

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7
Location #: 420224



Location Overview: Location is located in a 411 a. internal buffer zone.

Section/Township/Range: 7 7S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7
Location #: 420224



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7
Location #: 420224



Photo #9460 Location lacks stabilization.



Photo #8970 from inspection #699805435 conducted on 2/14/23.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7
Location #: 420224



Photo #9464 Location lacks stabilization



Photo #8970 from inspection #699805435 conducted on 2/14/23.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7
Location #: 420224



Photo #9466 Location lacks stabilization



Photo #9467 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7
Location #: 420224



Photo #9472 Insufficient tracking BMP at entrance to location.



Photo #8979 from inspection #699805435 conducted on 2/14/23.

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21-7

Location #: 420224

Network: Apr 3, 2023 at 12:20:35 PM M



Photo #9473 Insufficient track BMP at entrance to location.