


Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW

Location #: 334731



Location Overview: Location is located in a 411 a. external buffer zone.

Section/Township/Range: 3 7S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW
Location #: 334731



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW
Location #: 334731



**Photo #9480 Spill prevention and materials handling
BMP insufficient.**



**Photo #9479 Spill prevention and materials handling
BMP insufficient.**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW
Location #: 334731



Photo #9475 Location lacks stabilization.



Photo #9482 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW
Location #: 334731



Photo #9483 Location lacks stabilization.



Photo #9484 Location lacks stabilization

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW
Location #: 334731



Photo #9485 Location lacks stabilization



Photo #9489 Location lacks stabilization

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC HENRY-67S95W /3SWNW
Location #: 334731



Photo #9486 Insufficient tracking BMP at entrance to location.