

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2023

Submitted Date:

04/04/2023

Document Number:

708200081

FIELD INSPECTION FORMLoc ID 421847 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	
ZUNIGA, ERICA		ericazuniga@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421831	WELL	SI	12/01/2022	OW	123-33080	CASTOR FEDERAL LC 22-78HN	RI
421847	LOCATION	AC			-	LC22-04 MULTI	RI

General Comment:

This is a follow-up inspection to Field Inspection Report (Doc #696105696) and Operator submitted FIRR (Doc #403313316) to document corrective action compliance.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	It appears the the operator has managed the interim areas for the undesirable vegetation (e.g. mowing) and removed tumbleweed debris. During this inspection, high winds were encountered and tumbleweed debris was starting to accumulate again; Operator shall continue to manage the location and control/dispose of weedy debris. Refer to attached inspection photos.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	During this inspection, unknown material/fluid was observed on engine skid and will need to be properly disposed of. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 1002.f.(2)D and conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	04/11/2023
Type	UNUSED EQUIPMENT		
Comment:	It appears the operator has performed the corrective action and reinstalled the tin on the engine shed.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			
Comment:	It appears the operator has cleaned up the stained soil near the flow line riser; however, stained soil remains near the engine shed. Refer to attached inspection photos.				
Corrective Action:	Properly dispose of oily waste in accordance with 905.e. Corrective action date is being back-dated to when the corrective action should have been performed.				Date: 02/17/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	421831	Type:	WELL	API Number:	123-33080	Status:	SI	Insp. Status:	RI
Facility ID:	421847	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200100	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072309