

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2023

Submitted Date:

04/05/2023

Document Number:

705000239

FIELD INSPECTION FORMLoc ID 327128 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246406	WELL	SI	05/01/2022	GW	123-14203	BEEBE DRAW UPRR 32-17	PA
327128	LOCATION	AC			-	BEEBE DRAW UPRR-63N65W 17SWNE	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 246406 Type: WELL API Number: 123-14203 Status: SI Insp. Status: PA

Flowline

#1	Type:Non-Well Site	of Lines	
----	--------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Beebe Draw UPRR 32-17) has been plugged and abandoned. COGCC form 42 notice of start of plugging operations doc #403287973 received 01/12/2023. Fenced excavations were observed at the PA wellhead and facility/ battery areas. The OLF has been removed; bellhole excavations observed at flowline pipe removal pull points between WH & battery. COGCC form 42 notice of flowline abandonment completed doc #403365425 received 04/05/2023. The facility/ tank battery (428380) is being decommissioned; tanks and equipment removed. On location dump and process flowlines are being removed. No flowline risers were observed at WH or BH excavations. Excavation/ remediation work in progress (historical).

Corrective Action:

Date:

Facility ID: 327128 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000249	PA well and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074466
705000250	OLF pipe removal; bellhole excavations	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074467
705000251	Flowline pipe removed at facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074468