

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2023

Submitted Date:

04/06/2023

Document Number:

707800267

**FIELD INSPECTION FORM**Loc ID 424294 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10759

Name of Operator: ORGANIC ENERGY COMPANY LLC

Address: 1318 SMEDE HWY (HWY 92)

City: BROUSSARD State: LA Zip: 70518

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Bienvenu, Benjamin	281-300-5049	ben@organicenergyco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424295	WELL	PR	03/02/2012	OW	081-07666	ELLGEN 11-10-1	PR

**General Comment:**

On Wednesday 4/5/2023, I, Inspector Scott Ramsey and Kris Neidel, conducted a joint OGI camera inspection at Organic Energy Ellgen 11-10-1, at Location # 424294 in Moffatt county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

Wind was light and temperature was around 30 degrees. We observed a line heater next to the vertical heated separator. Both heaters were running. ECD was running with slight heat trace observed with OGI camera.

During this inspection the following possible compliance issues were observed:

1. Some areas of location show signs of lack of stabilization and and no evidence of tracking BMP's.
2. Random staining from previous inspection around well head still present therefore C/A date remains the same 11/14/2022.
3. Stored equipment (tubing) from previous inspection is still present therefore C/A date remains the same 11/14/2022.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: 1-833-616-1696/911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored equipment (tubing) from previous inspection is still present therefore C/A date remains the same 11/14/2022.		
Corrective Action:	Remove stored/ unused equipment	Date:	11/14/2022
Type	OTHER		
Comment:	Random staining from previous inspection around well head still present therefore C/A date remains the same 11/14/2022.		
Corrective Action:	Remove and dispose of properly stained material	Date:	11/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 424295	Type: WELL	API Number: 081-07666	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover.  
Access road was snow drifted in multiple areas.  
Some areas of location show lack of stabilization which in turn lead to tracking issues.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: Cloudy Temperature: (F)Assisting Staff Kris Neidel Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
10:15	AM	10:35	AM

Equipment
Oil Tank(s)
Separation Equipment
Wellhead(s)
Other

Comment: ECD was running with slight heat trace observed with OGI camera.Corrective  
Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800268	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074697</a>
707800269	OIG of production equipment(line heater)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074698">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074698</a>
707800270	OGI of ECD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074699">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074699</a>
707800271	OGI of ECD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074700">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074700</a>