

Inspection Photos

4/05/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702



Photo 1: Photos 1-2 taken from the Location. Photos show BMPs to stabilization the Location, and to minimize erosion, degradation and off-site sediment transport remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334702



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702



Photo 3: See comments under photo 3-5 taken from the cut slopes on the east end of the Location. Photos show BMPs to minimize erosion and degradation at the slopes remain missing or insufficient. Slopes lack stabilization.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702



Photo 4: See comments under photo 3.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702



Photo 5: See comments under photo 3. Photo shows sediment deposition due to lack of stabilization at the slopes of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334702



Photo 6: Anchor appears to have been removed.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702



Photo 7: Photos 7-8 examples showing various trash debris (liner material, rags, etc...) observed throughout the entire interim areas on the east end of the Location. .

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334702



Photo 8: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334702



April 5, 2023

Photo 9: Photo taken from the access road entrance ~1/2 south of the Location. Photo shows Operator has implemented a single row of “reusable trackout control mats”. BMP is not per good engineering practices, and is inadequate in length to allow for at least an entire tire rotation for most off-highway, or industrial vehicle tires used in O&G.