

Interim Reclamation and Stormwater Inspection

Date: 03/31/2023

Operator: FOUNDATION ENERGY MANAGEMENT LLC
- 10112

Location ID: 429231

Inspection Document #: 708200094

Weld County, CO

NENE Section 1 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photo 1. Water truck has been removed from the location.

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photos 2 & 3. The hydrocarbons appear to have been removed from the produced water pit and the wildlife exclusion netting appears to have been repaired and is adequate at the time of this inspection.

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photos 4 & 5. See comments in Photos 2 & 3.

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photo 6. It appears the Operator has removed/cleaned up the stained soil previously identified, however, additional stained soil was observed at the time of this inspection. The Operator shall inspect/repair all equipment to ensure it is in good working condition to prevent any possible leaks from the tank and associated piping.

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photo 7. Facing southwest towards adjacent farm ground. Rill erosion was observed at the time of this inspection and will require stormwater BMPs to prevent any additional erosion.

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photo 8. Facing northeast; see comments in Photo 7.

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 429231



Photo 9. Facing north from the northwest corner of the location; see comments in Photo 7.