

Interim Reclamation and Stormwater Inspection

Date: 03/31/2023

Operator: FOUNDATION ENERGY MANAGEMENT LLC
- 10112

Location ID: 331563

Inspection Document #: 708200095

Weld County, CO

SESE Section 36 T8N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: State-68N60W 36SESE
Location ID: 331563



Photos 1 & 2. Abandoned risers do not have plugs or OOSLAT installed.

Inspection Photos

Location Name: State-68N60W 36SESE

Location ID: 331563



Photos 3 & 4. Taken from the northeast corner of the pad. Photo illustrates that no apparent sediment laden stormwater has exited off location (left) and that the Operator appears to have backfilled the eroded areas and installed straw wattles as a BMP for the location (right).



Photo 5. It does not appear the straw wattles were installed per good engineering practices as they were not trenched in. Sheet flow of water could potentially run directly underneath the straw wattles if not installed properly.

Inspection Photos
Location Name: State-68N60W 36SESE
Location ID: 331563



Photo 6. See comments in Photo 5.

Inspection Photos
Location Name: State-68N60W 36SESE
Location ID: 331563



Photo 7. Overview of location with straw wattles; See comments in Photo 5.