

Chevron U.S.A. Inc. Associated Unit C 1 Location #314494



Entrance to location



Wellhead view

**Chevron U.S.A. Inc.
Associated Unit C 1
Location #314494**



Chemical containment is full



Full containment

**Chevron U.S.A. Inc.
Associated Unit C 1
Location #314494**



Traffic causing rutting and sediment migration

Lack of stabilization and vehicle tracking

**Chevron U.S.A. Inc.
Associated Unit C 1
Location #314494**



Traffic from lease road through vegetation area

Traffic turning off lease road across vegetation area

**Chevron U.S.A. Inc.
Associated Unit C 1
Location #314494**



Steel tubing not in service



Debris in front of control panel