

**Chevron U.S.A. Inc.  
LN Hagood A-15X  
Location #315317**



**West side access road**



**East across location**



**Chevron U.S.A. Inc.  
LN Hagood A-15X  
Location #315317**



**Entrance to location**



**Entrance to location**



**Chevron U.S.A. Inc.**  
**LN Hagood A-15X**  
**Location #315317**



**Wellhead view**



**Looking Southwest to West side entrance.**



**Chevron U.S.A. Inc.  
LN Hagood A-15X  
Location #315317**



**Berm erosion and sediment migration**



**Berm erosion with sediment migration**



**Chevron U.S.A. Inc.  
LN Hagood A-15X  
Location #315317**



**Sediment piles pushed downhill of location**



**Sediment pushed off location and downhill.**