

TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location # 335372



Wellheads – Photo #01894



Separators – Photo #01900



TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location # 335372



Tank Battery – Photo #01897



Inadequate Chemical Tank Secondary Containment Capacity – Photo #01895

TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location # 335372



Open-Ended Line – Photo #01898



Lack of Stabilization w/ Inadequate Tracking BMP –
Photo #01901

TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location # 335372



**Lease Road Degradation/Sediment Transport –
Photo #01904**