

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE

Location ID: 334653



Photo #9538 From entrance to location.



Photo #9539 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE

Location ID: 334653



Photo #9540 From entrance to location.



Photo #9541 Multiple places with flowline heating insulation open ended.