


Storm Water Management and Erosion control

Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE

Location #: 334653



Location Overview: Location is located in a high priority habitat area.

Section/Township/Range: 15 7S95W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE
Location #: 334653



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE
Location #: 334653



Photo #9543 Location lacks stabilization.



Photo #9544 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE
Location #: 334653



Photo #9545 Location lacks stabilization.



Photo #9547 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC CLEM JR.-67S95W /15NWNE
Location #: 334653



Photo #9551 insufficient tracking BMP at entrance to location



Photo #9552 insufficient tracking BMP at entrance to location