

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2023

Submitted Date:

04/06/2023

Document Number:

699805522

FIELD INSPECTION FORM

Loc ID 323779 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456946	Domestic Tap	AC	08/28/2018		-	Domestic Tap 4NESE	AC

General Comment:

COGCC Inspection Report Summary
 On 4/5/23 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap /4NESE. Location #456946 Garfield County Colorado
 While there, I observed the domestic tap is derived from the back side casing valve of well W 12-4. The tap has an in line fluid knock out followed by and fisher little Joe regulator. All fitting appear to be sufficient.
 This is a summary of the inspection report

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Barbed wire fence around domestic tap		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 456946 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
		Berms				
Gravel						

Comment: [Refer to document # 69980520 for comments](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805523	Photos for Insp. #699805522	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075143