

Inspection Photos

API: 071-09921

Operator: VECTA OIL & GAS LTD

Inspection Date: 4/6/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 4/6/2023

Inspection Photos



Photo 1. Facing north toward the wellsite. Most all of the equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 4/6/2023

Inspection Photos



Photo 2. There are still a few pieces of equipment that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 4/6/2023

Inspection Photos



Photo 3. The compacted soils were ripped but unsure if cross-ripping was performed to 18inches. Disturbed soils will need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 4/6/2023