

Inspection Photos

April 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 334690

Location Name: QUARTER CIRCLE-66S94W/33NESE

Inspection Document #: 702801420

Garfield County, CO

NESE Section 33 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: QUARTER CIRCLE-66S94W/33NESE
Location ID: 334690



Photo 1. Photo taken from the west shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801420

Inspection Photos
Location Name: QUARTER CIRCLE-66S94W/33NESE
Location ID: 334690



Photo 3. Photo shows unused equipment within the southernmost tank battery secondary containment.

Inspection Photos
Location Name: QUARTER CIRCLE-66S94W/33NESE
Location ID: 334690



Photo 4. Photo shows a tank manway cover is not fastened and partially ajar.



Photo 5. Photo shows bull plugs not installed on a tank line.

Inspection Photos
Location Name: QUARTER CIRCLE-66S94W/33NESE
Location ID: 334690



Photo 6. Photos show a berm at the south of the location is not stabilized. Rill erosion and sediment transport are evident.

Inspection Photos

Location Name: QUARTER CIRCLE-66S94W/33NESE

Location ID: 334690



Photo 7. Photos show a berm at the south of the location is not stable. Rill erosion and sediment transport are evident.

Inspection Photos

Location Name: QUARTER CIRCLE-66S94W/33NESE

Location ID: 334690



Photo 8. Photos show Scotch thistle in the northern (left) and southern (right) interim areas.

Inspection Photos
Location Name: QUARTER CIRCLE-66S94W/33NESE
Location ID: 334690




Photo 9. Photos show northern (left) and southern (right) interim areas.