

Stormwater Inspection

Date: 03/31/2023

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 317498

Inspection Document #: 708200091

Weld County, CO

SWNW Section 14 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 1. Sediment trap and straw wattles installed in the area previously experiencing erosion issues. It appears the Stormwater BMPs will be sufficient at controlling and managing stormwater for this location.

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 2. Rip rap structure/water bar placed at the entrance to the pad.



Photo 3. Straw wattles placed as check dams within the eroded areas. Blow sand from high winds have accumulated within the straw wattles and will require maintenance to ensure the BMPs are properly functioning.

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 4. Sediment trap installed at the southern end of the location appears to have been stabilized with rip rap material.

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 5. Additional sediment trap placed within the recently reclaimed portion of the location.

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photos 6 & 7. Taken from the southern end of the location. It appears the operator has removed the sediment that migrated off location and installed straw wattles as BMPs. Maintenance on straw wattles will be required to remove deposited blow sand.



Photo 8. Berm and ditch BMPs appear to have been compacted and additional BMPs have been implemented (check dams within ditch and straw wattles placed on the exterior portion of the berms).

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 9. See comments in Photo 8.

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 10. Facing southeast from the northwest corner of the location. Straw wattles will need to be maintained to ensure they are properly functioning in the future.

Inspection Photos
Location Name: April- 67N60W 14SWNW
Location ID: 317498



Photo 11. Road maintainer/drag observed being stored on location and will need to be removed. As a reminder, locations cannot be used to store equipment.