

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2023

Submitted Date:

04/07/2023

Document Number:

708200091

FIELD INSPECTION FORMLoc ID 317498 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
SCHNEIDER, JEFF	970-867-9437	jeff@schneiderenergy.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238513	WELL	PA	06/21/2021	OW	123-05372	APRIL 12-14	RI
317498	LOCATION	AC			-	APRIL-67N60W 14SWNW	RI

General Comment:

This is a follow-up inspection to Field Inspection Reports (#708200033) and (#708200054) and Operator submitted FIRR (#403359454) to document corrective action compliance.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	It appears the sucker rod and and pipe have been picked up and removed off location. However, during this inspection the road drag/maintainer was observed parked next one of the pits and will need to be removed from the location.		
Corrective Action:	Comply with Rule 606 and remove any unused equipment. Corrective action date is being backdated to when the corrective action should have been performed.	Date:	03/25/2023
Type	TRASH		
Comment:	No trash observed on the location at the time of this inspection.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>238513</u>	Type:	<u>WELL</u>	API Number:	<u>123-05372</u>	Status:	<u>PA</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>317498</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: During this inspection, Staff observed that robust BMPs were implemented with evidence of straw wattles around the entire perimeter, compacted berms, rip rap check dams within the ditch system, stabilized out flows and sediment traps, and straw wattles placed as check dams within the areas experiencing erosion. Although the location has more significant stormwater controls than before, high winds experienced during this inspection contributed to blow sand accumulations within the straw wattles that will require future maintenance in order to function properly. Refer to attached inspection photos for documentation.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200112	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075439