

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2023

Submitted Date:

04/07/2023

Document Number:

702801430

FIELD INSPECTION FORMLoc ID 324015 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------------------------------|
| , TEP | | COGCCInspectionReports@terraep.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|--------------------------|-------------|
| 211495 | WELL | PR | 07/19/1998 | GW | 045-07255 | MACKLEY RMV 85-34 | RI |
| 324015 | LOCATION | AC | | | - | MACKLEY-66S94W 34SWSW | RI |

General Comment:

On 4/5/2023, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at TEP ROCKY MOUNTAIN LLC's MACKLEY-66S94W/34SWSW Location #324015 in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Unmarked anchors
- Stormwater

Refer to the "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 211495 | Type: | WELL | API Number: | 045-07255 | Status: | PR | Insp. Status: | RI |
| | | | | | | | | | |
| Facility ID: | 324015 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | RI |
| | | | | | | | | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date **04/21/2023**

Two (2) anchors observed to be unmarked/markers are in disrepair.

Install proper anchor markers per Rule 1003.a.

1003b. Area no longer in use? Pass Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? P

Comment

Areas of the location not needed for production have been reduced and reclaimed. Interim areas appear vegetated with native shrubs (sagebrush, rubber rabbitbrush) and perennial grasses. However, full vegetation assessment and definitive species identification was not possible due to dormant season and grazing. Interim areas appear impacted by livestock. Hoof action and heavy grazing is evident throughout the interim areas. Cattle present on the location at the time of the inspection. A follow up inspection will be conducted during a future growing season to determine compliance with 1003 requirements.

Corrective Action

Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

| | | | | | | |
|---------------------------|--|--|--|--|--|------------|
| Comment: | | | | | | Date _____ |
| Corrective Action: | | | | | | |
| Overall Final Reclamation | | Well Release on Active Location <input type="checkbox"/> | | Multi-Well Location <input type="checkbox"/> | | |

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

| | | | | | | |
|--------------------|--|--|--|--|--|------------------|
| Comment: | It was observed in this inspection that the Location shows signs of lack of stabilization BMPs in some areas, as is evidenced by the presence of ruts. Tracking control BMPs to minimize/mitigate tracking and offsite sediment transport are missing or insufficient. | | | | | Date: 04/10/2023 |
| Corrective Action: | Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection. | | | | | |

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 702801431 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075686 |