

Construction and Stormwater Inspection

Date: 04/03/2023

Operator: NAVEX RESOURCES LLC - 10360

Location ID: 483129

Inspection Document #: 708200115

Kit Carson County, CO

SENE Section 10 T11S R45W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129




Photo 1. Location signs and approved Form 2A posted at the entrance to the location.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 2. Facing east along the access road. It does not appear that all of the topsoil has been salvaged from the access road. See Photos 3 & 4 for additional information.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photos 3 & 4. Close up photos of topsoil salvaged from the access road. Left photo illustrates approximately 3" of topsoil have been salvaged from the access road portion. Right photo depicts pothole from access road illustrating approximately 6" of topsoil remain that will need to be salvaged.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 5. Overview of pothole from access road.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 6. Facing west from the southeast corner of the location. Photo illustrates that the topsoil stockpiles have been temporarily stabilized with equipment tracking; longer term stabilization techniques should be implemented. Additionally, temporary stormwater BMPs (scarifying and straw wattles) observed around the entire pad.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129




Photo 7. Taken from the southeast corner; see comments in Photo 6.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 8. Facing west from the southern portion; see comments in Photo 6.



Photo 9. Facing northeast from the southwest corner; see comments in Photo 6.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 10. Western stormwater ditch BMP: see comments in Photo 6.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 11. Facing southwest from the northern portion; see comments in Photo 6.



Photo 12. Facing east towards the drilling pad. Photo illustrates cut and fill slopes appear to be stabilized with stormwater BMPs implemented at the western edge of the disturbance area; scarifying, straw wattles, and ditch and berm pictured.

Inspection Photos
Location Name: Travis 1-10
Location ID: 483129



Photo 13. Overview of drilling pad.