

Construction and Stormwater Inspection

Date: 04/03/2023

Operator: NAVEX RESOURCES LLC - 10360

Location ID: 483130

Inspection Document #: 708200117

Kit Carson County, CO

NWSW Section 12 T11S R46W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 1. Taken from the location entrance. Location signs and an approved copy of the Form 2A posted on location. Also pictured, vehicle track out pad.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photos 2 & 3. Close up photos of soil pothole taken from access road. Left photo illustrates that approximately 3” of topsoil were salvaged from the access road. Right photo depicts approximately 5” of topsoil remains on the access road and will have to be salvaged to be in compliance with Rule 1002.b.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 4. Overview of access road, illustrating that approximately 3" of topsoil was salvaged and stored on the southern side of the road.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 5. Facing north near the access road/location entrance. Photo illustrates that temporary stormwater BMPs (scarifying and straw wattles) were implemented. Photo also illustrates topsoil stockpiles salvaged from the pad area have been temporarily stabilized with equipment tracking observed.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 6. Facing east from the northwest corner; see comments in Photo 5.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 7. Facing southwest from the northeast corner; see comments in Photo 5.



Photo 8. Facing south from the northeast corner. Photo illustrates stormwater ditch BMP on the downslope/eastern portion of the drilling pad.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 9. Facing north from the southeast corner of the location. See comments in Photo 5.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 10. Facing west from the southeast corner; see comments in Photo 5.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photo 11. Facing north from the southwest corner, see comments in Photo 5.

Inspection Photos
Location Name: Pfaffly 1-12
Location ID: 483130



Photos 12 & 13. Overview of drilling pad from the northwest corner of the pad.