

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2023

Submitted Date:

04/07/2023

Document Number:

702401779

FIELD INSPECTION FORM

Loc ID 317921 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10528
Name of Operator: ARCH OIL & GAS LLC
Address: 16400 DALLAS PARKWAY SUITE 305
City: DALLAS State: TX Zip: 75248

Findings:

20 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Jeff	940-391-7210	jbrowning@matthewssouthwest.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240185	WELL	SI	03/01/2020	OW	123-07973	CUYKENDALL-LAUCK 2	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not updated to reflect current operator		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	05/07/2023
Type	BATTERY		
Comment:	Sign not updated to reflect current operator.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	05/07/2023
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil identified at various locations through out location.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	04/14/2023
Type	WEEDS		
Comment:	Dead weeds around the WH, tank battery and around the location.		
Corrective Action:	Comply with Rule 606	Date:	04/14/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Gas Meter Run has fabricated steel pipe		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PW vault has barb wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	barb wire		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Guy line anchors not marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	04/21/2023
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		

Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: gas engine			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	CONCRETE SUMP/VAULT		40.139760,-104.481330
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.139250,-104.481610
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Wells Served By Facilities Above

AirsID

API Number
123-07973

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Large empty rectangular area for detailed notes or data entry.

Inspected Facilities

Facility ID: 240185 Type: WELL API Number: 123-07973 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/15/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Submit test results to the COGCC

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 4-7-2023 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Arch Oil & Gas LLC Location name: Cuykendall-Lauck #2 API #05-123-07973 County: Weld Weather: Clear. Location: Dry. While there, I observed wellsite and tank battery, SI at the time of inspection. During this inspection, I observed the following possible compliance issues: 606 weeds: Dead weeds around the WH, TB and around the location, CA date 4-14-2023. 605.g signs general condition: WH & TB Signs not updated to reflect current operator, CA date 5-7-2023. 1002..(2).D self-inspection: Stained soil identified at many spots on location, CA date 4-14-2023. 1003 Guy line anchors: Guy line anchors are not marked, CA date 4-21-2023. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	04/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401780	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6075749