

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Apr 7, 2023 at 9:34:57 AM
CO



Apr 7, 2023 at 9:35:00 AM
CO

Photo # 4500 From entrance to location

Photo # 4501 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 4502 Location

Photo # 4503 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 4504 Location



Photo # 4505 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 4507 Debris



Photo # 4508 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



**Photo # 4509 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 4510 Lack of stabilization/Insufficient tracking
BMP's**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



**Photo # 4511 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 4514 Lack of stabilization/Insufficient tracking
BMP's**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



**Photo # 4515 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 4518 Lack of stabilization/Insufficient tracking
BMP's**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



**Photo # 4520 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 4521 Lack of stabilization/Insufficient tracking
BMP's**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



**Photo # 4522 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 4524 Lack of stabilization/Insufficient tracking
BMP's/vehicle tracking**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Apr 7, 2023 at 10:10:53 AM
CO



Apr 7, 2023 at 10:11:09 AM
CO

**Photo # 4525 Lack of stabilization/Insufficient tracking
BMP's**

Photo # 4526 Vehicle tracking/Insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 Pad

Location ID: 324047



Photo # 4527 Vehicle tracking/Insufficient tracking BMP's