

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



Photo # 4464 From entrance to location.

Photo # 4467 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



Photo # 4468 From entrance to location



Photo # 4465 location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



Photo # 4466 Location



Photo # 4469 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



Photo # 4470 Location



Photo # 4471 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4480 Meter calibration info not conspicuously posted**



**Photo # 4472 Failure to minimize surface disturbance/vehicle tracks into interim area/transport of sediment.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4473 Failure to minimize surface disturbance/vehicle tracks into interim area/transport of sediment.**



**Photo # 4474 Failure to minimize surface disturbance/vehicle tracks into interim area/transport of sediment.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4475 Failure to minimize surface disturbance/vehicle tracks into interim area/transport of sediment.**



**Photo # 84 Failure to minimize surface disturbance/vehicle tracks into interim area**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4496 Failure to minimize surface disturbance/vehicle tracks into interim area**



**Photo # 4483 Lack of stabilization/compaction**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4484 Lack of stabilization/insufficient tracking  
BMP's**



**Photo # 4485 Lack of stabilization/insufficient tracking  
BMP's**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4486 Lack of stabilization/insufficient tracking BMP's**



**Photo # 4488 Lack of stabilization/insufficient tracking BMP's**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



Apr 6, 2023 at 10:39:42 AM  
CO



Apr 6, 2023 at 10:39:58 AM  
CO

**Photo # 4489 Lack of stabilization/insufficient tracking  
BMP's**

**Photo # 4490 Lack of stabilization/insufficient tracking  
BMP's**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 524-21 pad

Location ID: 335244



**Photo # 4491 Lack of stabilization/insufficient tracking  
BMP's**



**Photo # 4492 Lack of stabilization/insufficient tracking  
BMP's**