

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4537 From entrance to location



Photo # 4538 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4539 Location



Photo # 4540 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4541 Location



Photo # 4545 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4546 Meter calibration info not conspicuously posted



Photo # 4547 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4548 Debris



Photo # 4551 Erosion/transport of sediment off location/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4552 Erosion/transport of sediment off location/insufficient BMP's



Photo # 4564 Erosion/transport of sediment off location/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4565 Lack of stabilization/compaction/Insufficient tracking BMP's



Photo # 4566 Lack of stabilization/compaction/Insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



Photo # 4568 Lack of stabilization/compaction/Insufficient tracking BMP's



Photo # 4569 Lack of stabilization/compaction/Insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 94-21 Pad

Location ID: 335210



**Photo # 4570 Lack of stabilization/Insufficient tracking
BMP's**



**Photo # 4574 Lack of stabilization/Insufficient tracking
BMP's**