

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2023

Submitted Date:

04/10/2023

Document Number:

699106626

FIELD INSPECTION FORM

Loc ID: 459852 Inspector Name: Burns, Adam On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459852	LOCATION	AC			-	DD08-02 Pad	AC

General Comment:

[Inspection due to Incident](#)
[Incident Report #403368890](#)

Inspected Facilities

Facility ID: 459852 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 4/10/23 at approximately 1142hrs I, Inspector Adam Burns, Conducted an on-site inspection to Incident Report #403368890 at Guttersen DD08-02 Pad of Chevron Location ID #459852 in Weld County, Colorado. While there, I was observing Chevron conducting a clean up to the incident that occurred. I was informed from the Chevron representative on location that the fence crew on 4/6/23 was placing fence posts around the gas lift shed while the location was shut in. While digging the holes the auger on the fence digger unknowingly struck the bulk flow line for the wells on location. Wells were returned back to production on 4/7/23 when chevron noticed oil, gas, and produced water flowing and released to surface approximately 10 BBLS of fluids were released. Wells were shut back in. Clean up and soil testing are in progress. This is a summary of the inspection report.</p>	burnsa	04/10/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106627	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077130