

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2023

Submitted Date:

04/10/2023

Document Number:

697504593

FIELD INSPECTION FORMLoc ID 421908 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dustin@uplandexploration.com	
		martin@rockiesresourcesllc.com	
		david@uplandexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421912	WELL	SI	02/01/2021	OW	123-33110	Wagner 11-65 11-1H	RI

General Comment:

This is a Stormwater Inspection for a shared access road addressing a previous corrective action along a portion of the access road that crosses a High Priority Habitat (Aquatic Native Species Conservation Waters) at Geary Creek.

An inspection was performed back on February 10, 2023 for Upland Exploration. At that time, COGCC staff, Chris Binschus, only issued a corrective action to Upland Exploration. It was brought to COGCC's attention on 4/7/2023 that this was a shared access road.

Location Construction

Location ID: 421908 CDP: _____

Comment: The Access Road Map within the Location file is not accurate- see Doc.# 2530506.

Corrective Action: Operator shall submit an accurate access road map via Form 4 Sundry Notice.

Date: 04/24/2023

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective
Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of the inspection on 2/10/2023, sediment discharge into Geary Creek from the access road was observed. Portions of the access road, east of Geary Creek, are not sufficiently stabilized and the south-facing fill slopes leading into Geary Creek are not stabilized. Operator has failed to prevent transport of sediment into a High Priority Habitat (Aquatic Native Species Conservation Waters). Refer to Photos 1-4.

Upland Exploration is in-process of completing the corrective action work but it is not complete.

Corrective Action: CCRP shall coordinate with Upland Exploration on the corrective action work to comply with Rule 1002.f.

The corrective action date is the date the issue was observed out of compliance.

Date: 02/10/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697504594	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6077367