

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2023

Submitted Date:

04/11/2023

Document Number:

712700003

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Pattillo, Curtis On-Site Inspection   
313550 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8725  
Name of Operator: BLACK RESOURCES, INC  
Address: 320 MUSTANG TRAIL  
City: GRANBURY State: TX Zip: 76049

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224454	WELL	TA	06/14/1990	GW	083-06519	STATE (OWP) 36-11	TA

**General Comment:**

SW Compliance Specialist Curtis Pattillo and Supervisor Steve Lawboski performed an early spring, snow covered rudimentary inspection of the access road, gate and partially observed the pad location.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	H2S warning sign on access road present.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wind sock present at well location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 224454 Type: WELL API Number: 083-06519 Status: TA Insp. Status: TA

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Snow covered ground.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700004	Picture of locks and gate.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6078433">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6078433</a>
712700005	Picture of location, H2S warning sign, wind sock.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6078434">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6078434</a>