

Inspection Photos

API: 055-06037

Operator: OXY USA INC

Inspection Date: 4/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 4/10/2023

Inspection Photos



Photo 1. Facing south along the main road. Grading of the road has pushed up the metal rebar and has pushed material and gravel off the roadway. There were a few other bent rebar observed along the road as well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 4/10/2023

Inspection Photos



Photo 2. There has been grading performed along the road however, gravel material has been pushed off the road causing additional disturbance. This material needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 4/10/2023

Inspection Photos



Photo 3. There has been grading performed along the road however, gravel material has been pushed off the road causing additional disturbance This material needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 4/10/2023

Inspection Photos



Photo 4. Facing southeast toward the well site. The gravel debris has mostly been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 4/10/2023