

Inspection Photos

API: 055-06012

Operator: OXY USA INC

Inspection Date: 4/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 1. Drone aerial photo of the location showing the excavated areas of the remediation project.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 2. Facing northwest toward the location.



Inspection Photos



Photo 3. Facing toward the produced water tank. The secondary berm around the tank is insufficient to contain a spill. Red arrow points to small berm which could easily be overtopped by a leak.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 4. There is oily fluid and stained soil at the pipe outlets of the tank.



Photo 5. There is oily fluid inside this container used for containment. This needs to be cleaned up and should be netted to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 6. Facing northwest at the location. The remediation area where tank was located remains open and the safety fence is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 7. Facing where tank was located which remains an open excavation due to active remediation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 8. The perimeter wattles are degraded and need to be replaced and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 9. Facing northwest toward the excavated area which has been back. There was chalky colored soil material used to backfill the area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 10. The panels which were around the excavation have fallen over and need to be removed or placed at the other open excavation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 11. Facing southeast at the location. The stored impacted soils have been removed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023

Inspection Photos



Photo 12. Facing toward the northwest side of the location. It appears the chaulky white soils were pushed out in this area. All unneeded disturbed areas will need to be reclaimed per 1003 rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06012 | Date: 4/10/2023