

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5006 From entrance to location



Photo # 5007 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5008 Location



Photo # 5009 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5010 Location



Photo # 5011 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad
Location ID: 323886



Photo # 5014 Meter calibration info not conspicuously posted



Photo # 5015 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5016 Debris



Photo # 5027 Debris



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad
Location ID: 323886



Photo # 5041 Debris



Photo # 5042 Debris



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5043 Debris



Photo # 5020 Containment liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5021 Containment liner needs maintenance



Photo # 5025 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5047 Tank missing required information



Photo # 5024 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5029 Lack of stabilization/compaction



Photo # 5031 Lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad
Location ID: 323886



Photo # 5034 Lack of stabilization/compaction



Photo # 5036 Lack of stabilization/compaction



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Apr 11, 2023 at 11:25:06 AM
CO



Apr 11, 2023 at 11:25:30 AM
CO

Photo # 5039 Lack of stabilization/compaction

Photo # 5040 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 5044 Lack of stabilization/compaction